



İstanbul :

25.04.2008

Sayı  
Our Reference : 2290Konu  
Subject : Amerikan Sahil Güvenliği'nin Limanlarda Uygulayacağı  
Yaptırımlar ( Port Security Advisory 3-08 ) Hk.**Sirküler : 206 /2008****Sayın Üyemiz,**

İlgi : Hacı İsmail Kaptanoğlu Tic.Ltd.Şti.'nden alınan 25/04/2008 tarihli yazısı.

İlgi yazı ile; U.S.Department of Homeland Security United States Coast Guard'nun 18 Mart 2008 tarihli Liman Güvenliği Tavsiye Notu (Port Security Advisory (3-08)), anti-terör uygulamalarını hayata geçirememiş ülkelerin gemi ve işletmelerine uygulanacak yaptırımlar ve alınması gereken önlemler ile ilgili Port Security Advisory (3-08) nin yayımlandığı bildirilmektedir.

Rehber'de, anti-terör uygulamalarını hayata geçirememiş ülkeler; İran, Kamerun, Ekvator Ginesi, Gine Bissau, Endonezya, Liberya, Moritanya ve Suriye olarak sıralanmakta olup, Amerikan Limanlarına gelmeden önce son uğradığı beş ülke arasında anılan ülkelerden biri bulunan gemilerin alması gereken önlemlerle ilgili hususların da yer aldığı Port Security Advisory (3-08) Ek'te yer almaktadır.

Bilgilerinize arz ve rica ederiz.

Saygularımızla,

Murat TUNCER  
Genel Sekreter

EK : Port Security Advisory (3-08)

**Gereği :**

- Tüm Üyeler (Web)
- Türk Armatörler Birliği
- S/S Gemi Arm.Motorlu Taşıyıcılar Koop.
- VDAD
- Koster Armatörler Derneği
- Türk Uzakyol Gemi Kaptanları Derneği
- TÜRKLİM
- Gemi Sahibi Firmalar

**Bilgi :**

- YK Bşk.ve Üyeleri

SRK 291-295-28.4.08

sirkuler 1/1/08



U.S. Department of  
Homeland Security  
United States  
Coast Guard



Date: 18 March 2008

Contact: Mr. Mike Brown  
(202) 372-1081

## Port Security Advisory (3-08)

### A. Background:

The Maritime Transportation Security Act of 2002 (MTSA) has mandated that the United States Coast Guard evaluate the effectiveness of anti-terrorism measures in foreign ports and provides for the imposition of conditions of entry on vessels arriving to the United States from countries that do not maintain effective anti-terrorism measures (MTSA, 46 USC § 70108).

Iran is the most recent country the Coast Guard has determined to be not maintaining effective anti-terrorism measures.

### B. Countries Affected:

The Coast Guard has determined that ports in the following countries are not maintaining effective anti-terrorism measures:

**Iran** (Effective 2 April 2008)

**Cameroon** (with the exception of the Ebome Marine Terminal, the Quai GETMA (LAMNALCO Base) facility, and the Société Nationale de Raffinage (SONARA) terminal)

**Equatorial Guinea** (with the exception of the ports of Ceiba, K-5, Luba, Punta Europa, and Zafiro)

**Guinea-Bissau**

**Indonesia** (with the exception of Banjarmasin Port; Belawan Multi-Purpose Terminal; Caltex Oil Terminal Dumai; Jakarta International Container Terminal; Pelindo II Conventional Terminal Jakarta; Pertamina Unit Pengolahan II Dumai; Pertamina Unit Pengolahan V Balikpapan; PT Badak Bontang Natural Gas Liquefaction; PT Indominco Mandiri Bontang [Bontang Coal Terminal]; PT Multimas Nabati Asaha; PT Pelabuhan Indonesia I Cahang Dumai; PT Pertamina Unit Pemasaran III Jakarta; PT Pupuk Kaltim Bontang; PT Terminal Petikemas Surabaya; Semarang International Container Terminal; and Seripah Terminal Total E&P Indonesia Balikpapan)

MORE

This fax was received by Deniz Ticaret Odasi. For more information, visit: <http://www.denizticaretodasi.org>

This fax was received by Deniz Ticaret Odasi. For more information, visit: <http://www.denizticaretodasi.org>

**Liberia**

**Mauritania (with the exception of the Chinguetti Terminal)**

**Syria**

**C. Actions Required by Vessels Visiting Countries Affected:**

All vessels arriving to the United States that visited the countries listed in paragraph B (with exceptions noted) during their last five port calls must take actions 1 through 5 listed below while in the countries listed in paragraph B as a condition of entry into U.S. ports:

1. Implement measures per the ship's security plan equivalent to Security Level 2;
2. Ensure that each access point to the ship is guarded and that the guards have total visibility of the exterior (both landside and waterside) of the vessel. Guards may be:
  - provided by the ship's crew, however, additional crewmembers should be placed on the ship if necessary to ensure that limits on maximum hours of work are not exceeded and/or minimum hours of rest are met, or
  - provided by outside security forces approved by the ship's master and Company Security Officer.
3. Attempt to execute a Declaration of Security;
4. Log all security actions in the ship's log; and
5. Report actions taken to the cognizant U.S. Coast Guard Captain of the Port prior to arrival in the U.S.

Vessels that visited the countries listed in paragraph B (with exceptions noted) during their last five port calls will be boarded at sea by the Coast Guard to ensure the vessel took the required actions. Failure to properly implement the actions listed in paragraph C.1 through C.5, will result in denial of entry into the United States.

However, vessels that visited Monrovia, Liberia during their last five port calls prior to entering the United States will not normally be boarded at sea by the Coast Guard unless other targeting factors apply, nor will these vessels be required to provide armed security guards while in ports of the United States.

MORE

**D. Actions Required by Vessels in U.S. Ports:**

While in U.S. ports, all vessels subject to conditions of entry in paragraph B (with exceptions noted), are required to ensure that each access point to the ship is guarded by armed security guards and that they have total visibility of the exterior (both landside and waterside) of the vessel. The number and location of the guards must be acceptable to the cognizant U.S. Coast Guard Captain of the Port.

However, the requirement to ensure that each access point to the ship is guarded by armed security guards does not apply to vessels that visited Monrovia, Liberia during their last five port calls prior to entering the United States.

**E. Countries Subject to Additional Port State Control Targeting:**

Vessels arriving from the following countries remain subject to increased port state control targeting, including at sea boardings:

**Democratic Republic of the Congo**

**Madagascar (with the exception of the ports of Diego-Suarez, Majunga, and Toamasina)**

While not required as a condition of entry, if a vessel takes the steps outlined in paragraph C 1 through 5, the vessel's security posture will be considered and reflected in the scope, intensity and duration of the Port State Control measures. Taking these steps does not guarantee vessels will not be subject to additional measures.